
Section A. Facility Data				
Facility No.	223			
Facility Descriptor:	Nitrogen Plant			
Project:	RISS			
Date of Demolition:	05/11/04			
Additional Information:	Attached			
(Must include information on environmental releases and conditions of site at turnover to Environmental Restoration)				

Section B. Final Characterization Data Reconnaissance Level Characterization Report		
(concurrence received)	01/10/03 Area 3, Group 1	C 18-001243
In-process Characterization	N/A	
Pre-Demolition Survey Report (approval received)	RLC functioned as PDS	R 1A-001246 10-7-02
Post-Demolition Survey Report (as necessary)	N/A	

<u></u>					
Section C. Waste Data (complete cat	egories as appropriate)				
Sanitary Disposal					
Disposal Site:	BFI Foothills Landfill, Golden CO				
Waste Volume (m³):	2029				
Waste Weight (tons):	1360.84				
Additional Information:	Waste includes perlite from cooling tower				
Hazardous Disposal					
Disposal Site:	Kettleman Hills Facility, Kettleman City, CA or Bethlehem Apparatus				
	Co., Hellertown, PA.				
Waste Volume (m³):	N/A				
Additional Information:	Circuit boards, fluorescent lamps, Hg switches, etc. were moved to a				
	RFCA Temporary Unit and combined with like waste streams for				
·	disposal.				
TSCA Waste Disposal (other than					
ACM)					
Disposal Site:	N/A				
Waste Volume (m ³):	<1				
Additional Information:	PCB ballasts were sent to the landfill as PCB Bulk Product Waste co-				
Additional anior mation.	mingled with building debris.				
Asbestos Waste Disposal	NUA				
Disposal Site:	N/A				
Waste Volume (m ³):	N/A				
Additional Information:	N/A				
Low-Level Waste Disposal	N/A				
Additional Information:	N/A				
Low-Level Mixed Waste Disposal	N/A				
Additional Information:	N/A				
Recycled Material	99.3 Tons of metal sent to Iron and Metals recycle, Inc.				
Additional Information:					
Property Disposition					
Receiver Locations (major items only):	CCH Equipment Company, Dallas TX (Tanks 233 and 234)				
Additional Information: T233 & T234	Corr Equipment Company, Danies 171 (Tunto 255 and 251)				
Auditional Information. 1255 & 1254					

Section D. Approvals Kaiser-Hill Project Manager	(J FRETROT	184	m	10/13/09
	Name/Signature	' 0 '		Date




Additional Facility Information

Building 223 was a 3500 sq. ft. Nitrogen Plant constructed in 1991. This facility was a steel frame building built on a concrete foundation. The walls and the roof were corrugated metal sheets mounted to a steel frame. The facility included two large purification tanks (Tanks 233 and 234) on the north side of the building, and a cooling tower on the west side of the building. Building 223 was located near PAC 300-156.1 "Building 371 Parking lot," which received a No Further Action (NFA) approval in 2001.

Building 223 housed the equipment for separating nitrogen from ambient air. Filtered air was compressed and purified in a heat exchanger. It was then passed through a distillation chamber where nitrogen was separated from the oxygen based on the differences in their liquefaction temperatures. The nitrogen was then piped throughout the plant. Excess nitrogen was liquefied and stored for future use. Building 233 had the following utilities; water, sanitary, electric, gas, steam heat, and an overhead sprinkler system.

The entire facility (structure, tanks, and slab) was removed during D&D activities, and sent offsite for disposal at the BFI Foothills Landfill in Golden, CO or recycle at Iron and Metals Recycle, Inc. in Denver, CO. Prior to D&D, Tanks 233 and 234 were removed and relinquished to the CCH Corporation of Dallas, TX through the RFETS property management system. The cooling tower contained approximately 150 cubic yards of perlite that was removed during an effort separate from the primary facility demolition, and sent offsite for disposal at the BFI Foothills Landfill in Golden, CO.

All overhead utilities (steam and natural gas) were completely removed from the B223 area under a site-wide effort that will be documented in a separate close out report. Water and sewer lines were removed to the disconnect point indicated on the attached map. The underground electrical service was disconnected at the building and all wires removed from the conduit. The conduit line remains at a depth greater than 3 feet below grade as indicated on the attached map. There is no expected contamination remaining for ER activities. The only additional work at this site will be to establish the final site grade.



3/2